


MATCH TO SHEET 264

MATCH TO SHEET 286


 PREPARED BY:
 AERCON PHOTOGRAMMETRIC SERVICES, INC.
 3500 KAISER COURT, SUITE LL-10
 WILLOUGHBY, OHIO 44094
 (216) 946-6277



275	274	273
284		282
296	295	294

DILWORTH MINE
 DATE OF PHOTOGRAPHY: MARCH 3, 1995
SHEET 283