

FIT TO 5

FIT TO 3

PERMIT NO. 3084153
 PREPARED BY OWNER & OPERATOR CONSOLIDATION COAL COMPANY

CONSOLIDATION COAL COMPANY
 DILWORTH MINE
 PITTSBURGH SEAM OWNED OR CONTROLLED BY
 CONSOLIDATION COAL COMPANY
 WHEATON COUNTY, PA.

SCALE: 1" = 200' SURVEY DATE: 6-30-94

LEGEND

- CONTEMPLATED MINING 7-1-94 to 12-31-94
- MINING FROM 1-1-94 TO 6-30-94
- PROTECTED STRUCTURES
- SUPPORT AREA
- MINING COMPLETED AREA
- DWGS BUILT AFTER ACT OF 1966
- 2.A.A.

PARTIAL SECONDARY MINING COMPLETED

Partial mining areas, projected or unprojected, which are to be mined by 12/31/94 are shown in yellow. Areas to be mined from 1/1/94 to 6/30/94 are shown in white. Areas to be mined after 6/30/94 are shown in light gray. A minimum of 50% must be mined in areas.

Safety walls shall not exceed 60' in unconsolidated support areas. No secondary mining is permitted in support areas. No secondary mining is permitted in areas to be mined after 6/30/94.

All coal in the support area in longitudinal sections to be sold, except for surface and prospects as shown, projected entries and prospects are typical, and may vary due to mining conditions.

SUBSIDENCE CONTROL PLAN LINE

