



FIT TO 4

PERMIT NO. 3084133  
 PREPARED BY OWNER & OPERATOR CONSOLIDATION COAL COMPANY

CONSOLIDATION COAL COMPANY  
 DILWORTH MINE  
 PITTSBURGH SEAM OWNED OR CONTROLLED BY  
 CONSOLIDATION COAL COMPANY  
 GREENE COUNTY, PA.

SCALE: 1" = 200' SURVEY DATE: 6-30-94

LEGEND

- CONTEMPLATED MINING 7-1-94 to 12-31-94
- MINING FROM 1-1-94 TO 6-30-94
- PROTECTED STRUCTURES
- SUPPORT AREA
- MINING COMPLETED AREA
- DMS BUILT AFTER ACT OF 1966
- PARTIAL SECONDARY MINING COMPLETED
- SUPPORT AREAS
- NEW ACCESS ROAD
- SUBSIDENCE CONTROL PLAN LINE

ENTRY WIDTH SHALL NOT EXCEED 40' IN DESIGNATED SUPPORT AREAS. No secondary mining operations for 6 months if primary mining is not progressing. Entries to crosscut shall 40' typical and may vary due to actual mining conditions.

OIL & GAS WELL AREAS SHALL BE MINED IN ACCORDANCE WITH THE APPROVED WELL COLLAR PERMIT NUMBERS SHOWN ON THIS WELL. ALL COAL IN THE SUPPORT AREA IN CROSS-CUT SECTIONS TO BE SOLD EXCEPT FOR ENTRIES AND CROSSCUTS AS SHOWN. PROTECTED ENTRIES AND CROSSCUTS ARE TYPICAL AND MAY VARY DUE TO MINING CONDITIONS.