



PERMIT NO. 00841815
 PREPARED BY OWNER & OPERATOR CONSOLIDATION COAL COMPANY

CONSOLIDATION COAL COMPANY
 DILWORTH MINE
 PITTSBURGH SEAM OWNED OR CONTROLLED BY
 CONSOLIDATION COAL COMPANY
 WENDE COUNTY, PA.

SCALE: 1" = 200'
 SURVEY DATE: 12-31-95

LEGEND

- CONTINGENT MINING 5-1-96 TO 6-30-96
- MINING FROM 6-30-96 TO 12-31-96
- STRUCTURE
- PROPOSED STRUCTURE MINING PRIOR TO 6-30-96
- MINING COMPLETED AREA
- ADJACENT STRUCTURE
- PARTIAL SECONDARY MINING COMPLETED
- PROPOSED
- ADJACENT

PARTIAL SECONDARY MINING COMPLETED: Partial mining areas, proposed or completed, are shown with the 30' contour lines. The 30' contour lines are shown in the same direction, indicating that they are not to be mined. A minimum of 50% test will remain in stock.

ENTRY WIDTH SHALL NOT EXCEED 16' IN DESIGNATED SUPPORT AREAS. An inventory listing provided for 12 months. If not, mining is not proposed. Entries & crosscuts shall be typical and may vary due to actual mining conditions.

OIL & GAS WELLS AREAS SHALL BE MINED IN ACCORDANCE WITH THE APPROVED WELL COLLAR PLANS NUMBERED BEHIND OR BACK WELLS. ALL COALS IN THE SUPPORT AREA IN LONGWELL SECTIONS 71 BE SOLD, EXCEPT FOR BUTTES AND COALS AS SHOWN. PROPOSED ENTRIES AND CROSS CUTS ARE TYPICAL AND MAY VARY DUE TO MINING CONDITIONS.

MINING CONTROL PLAN LINE

MODULE 19.3 REVISED 4-8-96
 5-15-97

Fit to 22

Fit to 20