



**FATALITY**

VICTIM - JOHN GRACHEN - ASSISTANT MINE FOREMAN  
 CHECK NO. 6105  
 TIME 9:08 P.M. NOV. 7., 1950.  
 PLACE NO. 6 ROOM 19 BUTT 26 FACE.  
 EXPLANATION: TRACK MOUNTED DRILL WAS PROCEEDING TO WORKING PLACE AND DERAILED WHERE SHOWN. DRILL OPERATOR COULD NOT RERAIL DRILL WITH ITS OWN POWER. LOCOMOTIVE CAME AND WAS ATTEMPTING TO REPLACE DRILL ON TRACK, WHEN FALL OF SAND ROCK CAME DOWN CAUSING FATAL ACCIDENT.  
 EYE WITNESS; MIKE STICHEN, MOTORMAN

JONES & LAUGHLIN STEEL CORPORATION		
VESTA COAL DIVISION, CALIFORNIA., PA.		
MINE NO. 4 - JOHN GRACHEN		
FATALITY - No 6 ROOM 19 BUTT 26 FACE		
DR. H.C.E	DATE: NOV. 9., 1950	C-1066
TR. CE	SCALE = ABOVE	