Nick Wohav, Single Check Nº 335 with his buddy Alex Lyskans Check Nº 358 were slabbing entry. While waiting on the road men to finish the track work in their working place. In order to provide proper clearance on the side of the entry it was necessary to remove about 12 inches of Coal at this point. The coal and slate was hard, firm and solid, and after the coal had all been removed from under the slate the men were having trouble getting the slate down. Wo har attemped to go under one end of it, when it suddenly let go, one end striking the side of the car, the other end pining him against the rib, Causing contusion of the back with brush burns.

Time of Accident 11.22 A.M.

Peice of Rock Tlong-19" Wide-6Thick 0 13 Room. —>

21 Butt-15:Face.

Drain.

Breakthrough

o Posts.

MRock.

+ Victim.

THE VESTA COAL CO. CALIFORNIA PA.

MINE. Nº 4. PLAN OF 21 Butt 15 FACE: NICK WOHAR ACCIDENTS/10/54.

DATE. 5/16/34.

SCALE. 1'=10'.

D. 689.