

GOB AREA EXAMINED BY FIRE BOSS
AT 5¹⁰ AM. - QUIET AT THAT TIME -

GOB AREA STARTED TO WORK ABOUT 7 AM.
AT TIME OF THE ACCIDENT.

FIRE BOSS DATE HERE →

GOB
ROW OF BREAKER POSTS

VICTIM INJURED HERE

THIS POST SET AFTER
THE ACCIDENT

PIECE OF ROCK THAT HAD BLOOD STAINS ON IT,
SUPPOSED TO HAVE STRUCK VICTIM'S HAND.

MACHINE CUTTING AT
TIME OF ACCIDENT


CROSS-BARS

LEG OF TIMBER

O FACE A.C.

RAILS

MARCH 22-1934 7:00 A.M.
GEORGE TIRPAK WAS STANDING AT POINT
MARKED ⊕ WATCHING MACHINE MEN CUT
HIS PLACE WHEN A FALL OF ROCK
KNOCKED HIM DOWN. IMMEDIATELY A
SECOND FALL STRUCK & CRUSHED HIS
LEFT HAND.



SECTION A-A.

THE VESTA COAL CO.
CALIFORNIA, PA.

MINE NO 6 SKETCH AT
LOCATION OF GEO. TIRPAK
ACCIDENT. MAR. 22-1934.

DR. E.R.C. 3-24-34
TR. G.H.E. SCALE 1" = 10'-0"

D-680